


DURABLE • RE-USABLE • WATERPROOF • CHEMICAL RESISTANT



[Figure 1] Measure each fitting from center to outer edge of fitting. (Include flanges and bolts if applicable.)

[Figure 2] If there is more than one fitting within a 3ft. section, measure from center of fitting to center of fitting.

[Figure 3] For each fitting measure the diameter or circumference of the widest section of the fitting, including any heat tracing. (Utilize Dragon Jacket measuring rings if available.)

[Figure 4] If there are any lines/fittings with clearances less than 1ft. please note and measure the distance.

[Note] Circumference of heat tracing may be provided if Dragon Jacket measuring rings aren't available.

